axis 34. The major axis 32 has a <u>first</u> dimension 36 that is greater than the diameter 38 of the conductive pads 16, 22. The regions of the conductive pads 16, 22 proximate the major axis 32 of the conductive pads 16, 22 are exposed or "un-captured" by the masks 26, 28. In contrast, the minor axis 34 has a <u>second</u> dimension 40 that is less than the diameter 42 of the conductive pads 16, 22. In regions 44, the conductive pads 16, 22 are partially covered or "captured" by the masks 26, 28.